




Revised 04/2010

10 Ton Aluminum Ratchet Jacks

A1022 & 22B REPAIR PARTS SHEET



ITEM NO.	DESCRIPTION	PART NO.	
		A1022	22B
1	Housing	N/A	N/A
2	Socket	90586	90586
3	Rack Bar	90968	90968
4	Cap	•	•
5	Lifting Pawl	90588	90588
6	Retaining Pawl	90589	90589
7	Trunnion Bearing (2 required)	+	+
8	Key (2 required)	***, +	***, +
9	Spring Link Lever	90275	90275
10	Spring Link Complete	+	+
11	Retaining Pawl Pin Assembly	***	***
12	Cap Pin	***, •	***, •
13	Side Plate	90965U	90965U
14	Wearing Plate	+	+
15	Handle	41192	41192
16	Rev. Lever Exp. Rivet.	***	***
17	Reversing Lever	90970	90970
18	Cotter Pin (3 required)	***, +	***, +
19	Side Plate Cotter Pin	***	***
20	Handle Rivet (2 required)	***	***
22	Capacity & Instruction Label	+	+
***	HARDWARE KIT COMPONENTS	RKA102201	RK22B01
+	REPAIR KIT	40562	40562
•	CAP KIT COMPONENTS	RKA1022B02	RKA1022B02

NOTE: HOUSING ARE NOT AVAILABLE AS SERVICABLE ITEMS.